

# NOMEX FABRIC CARE INSTRUCTIONS

## CARE INSTRUCTIONS

Fireproof equipment in NOMEX fabrics are very sensitive to sunlight, sunlight exposure will gradually change the fabric to a yellow color.

When cleaning NOMEX products please machine wash using neutral washing powder and a maximum water temperature of 30 Degrees Celsius using a normal washing cycle.

If there are fireproof prints on the overalls or underwear NEVER DRY CLEAN.

If there are fireproof prints on the overalls or underwear AVOID ANY CONTACT WITH FUEL VAPOURS AND SOLVENTS because this may permanently damage the prints.

To avoid damage to NOMEX fabric, close/ do-up any zips, velcro and reverse the garments inside-out. If there are velcro badges on the garments please protect these when washing.

Dry the garments reversed (inside-out) and away from direct sunlight until the garment is completely dry. Avoid putting wet garments (after use or after washing) in a closed bag.

Do not use aggressive products ( ie bleach, oxygen active products ) that may damage the fabrics, components, embroidery and printed applications.

Ensure any velcro and zippers are closed to avoid damage during the washing machine cycle.

Avoid automatic drying processes.

Any damage to the garment caused by improper maintenance will invalidate any warranty on the product.

The colors of NOMEX products have a resistance index of 3 based on a graduation scale of 0 to 5, for this reason it is important all care is taken.

All materials / fabrics used are 100% purchased in Italy and garments are completely manufactured in Italy.

For more information call 1(818) 747 3530, visit [www.freemusa.com](http://www.freemusa.com) or call your dealer.